Item No.
 5d attach_1____

 Date of Meeting
 May 28, 2013_____

Photos of Cracks and Ponding on Topping Slab




Photo of Water Leaks in the Station



