



Existing Site Condition Photographs:



1) South end dolphins (3) and gangway, looking south



2) South end walkway looking north