



1. Atrium view of Roof Beam at top of Clerestory Window



2. View Along Length of Beam

Pier 69 Roof Beam Rehabilitation (CIP #C800698)
Photos 1 Thru 6



3. Example of Beam Deterioration where repair work was performed
(*loose concrete was removed and reinforcement was coated*)



4. Close Up View

Pier 69 Roof Beam Rehabilitation (CIP #C800698)
Photos 1 Thru 6



5. Exposed Window Connection Anchor Bolt



6. View of Bottom of Beam Showing Reduced Section and Exposed Reinforcement