Item No.: 4d\_Supp Date: September 13, 2016

# Terminal 91 Building C-173 Roof Overlay



## **Building C-173 Roof Overlay**



Existing C-173 Roof Approximately 29 Years Old

#### **Existing Roof Elements**



Abandoned mechanical unit



#### Underside of abandoned mechanical unit

**Existing Roof Top Mechanical Elements** 

#### **Existing Deteriorated Roof Elements**



Underside rusted canopy area



Hole previously repaired with coating



Hole previously repaired with coating



Rusted underside of roof panel



Previous repair of metal roof at rusted location



Mechanical room penetrations

**Existing Deteriorated Roof Elements** 

## **Incorporate Sustainable Elements**

- Increase Insulation Value
- Utilize Reflective Overlay Material
- Recycling of Demolished Materials
- Durable Roof System that can last 30 years as specified

#### The project will also consider:

• Bio filtration units at the downspouts

### **Project Alternatives Considered**

Alternatives	Description	Cost Implications [Solar]
Alternative 1	<ul> <li>Maintain Status Quo.</li> <li>Continue to pay maintenance cost. (Approximately \$9.8K/yr)</li> </ul>	\$9.8K
Alternative 2	<ul> <li>Coat Roof with roll-on Coating System (10 year life)</li> <li>Add Fall protection and Security ladders</li> </ul>	\$2.34M
Alternative 3	<ul> <li>Replace Roof with PVC membrane (30 year life)</li> <li>Add Fall protection and Security ladders</li> <li>Install Thin Film solar panels</li> </ul>	\$1.56M [\$944K]
Alternative 4	<ul> <li>Replace Roof with PVC membrane (30 year life)</li> <li>Add Fall protection and Security ladders</li> <li>This is the recommended alternative</li> </ul>	\$1.56M

### **Next Steps**

- Complete Design
- Request Construction Authorization
- Construction Starts
- Construction Complete

4<sup>th</sup> Quarter 2016 1<sup>st</sup> Quarter 2017 2<sup>nd</sup> Quarter 2017 4<sup>th</sup> Quarter 2017

#### **Roof Overlay Project Schedule**