



Item No.:
Meeting Date:


4d_Supp
October 27, 2015

P69 Roof Beam Rehabilitation


P69 Roof Beam Rehabilitation




Pier 69 – Third Floor




Existing Conditions



Proposed Beam Covers



05/2015 – Mockup of detail



Preventative Maintenance

- Condition Assessment
- Concrete spall Repair
- Rebar corrosion control
- Crack repair

