### PHIL RIISE PRESIDENT

## SEAVIEW BOATYARD & YACHT SERVICE




# Environmental Leadership in a Highly Regulated Industry




















Seaview Boatyard















### BEST MANAGEMENT PRACTICES (BMPs)

#### **EVERYONE MUST COMPLY**

- All bottom paint prep work, spray painting or sand blasting must be performed by Seaview Boatyard personnel.
- 2. No wet sanding or scrubbing of bottom paint at any time.
- Grinding and power sanding above the waterline must be contained by tenting (no fugitive dust) or performed with
- approved vacuum sander. Only Seaview personnel may
   grind or sand bottom paint.
- Boat stalls must be swept or vacuumed daily. Do not hose down stalls. Based on job scope, ground tarping may be required.
- Contact yard store for disposal of all hazardous materials including oil, fuels, solvents, anti-freeze, bilge water, ballast water, and gray water.
- All paint cans, brushes, rollers, roller trays, etc. must be in a containment tray. Trays are available for loan in the yard store. Cans should be sealed at all times, not left open during job.

NON COMPLIANCE WITH BMPs WILL RESULT IN A MINIMUM \$500 FINE

IMMEDIATELY REPORT ANY HAZARDOUS MATERIAL SPILLS TO YARD STORE OR YARD OFFICE FOR ASSISTANCE AND SPILL CONTAINMENT KIT

DO NOT SHIFT STANDS PADS OR BLOCKING

Use of secondary containment trays is required for all paint cans.

Trays are available at the yard store.



















































Two generations of commitment to environmental leadership, recognized by agencies and organizations throughout Washington.









