

Terminal 91 Northwest Fender Replacement

Project Location




Current Condition




- 70% of piles show deterioration
- 30% of piles currently broken, split or hollowed



Proposed Replacement



Schedule



Questions?