
Item No. Date of Meeting

\_\_\_\_5d attach\_2\_\_\_\_ \_\_\_May 28, 2013\_\_\_\_

## SEA-TAC INTERNATIONAL AIRPORT






Figure 1: Parking Limits at North Satellite Apron

**Sectional View of the NSAT STS Lobby and Tunnel**. Failing slab (and membrane) is directly above the STS lobby.

