

SBM Central Seawall
Existing Condition and Aerial View

Item No.: 4b_Attach
Date: May 6, 2014



Seawall Aerial View (Looking South)



Seawall Overview (at zero tide)

SBM Central Seawall
Existing Condition and Aerial View



Current Lagging Degradation



Existing Condition