Item No.:4e suppMeeting Date:June 27, 2017

Pond Netting Repair

Seattle-Tacoma International Airport





Project Locations






Structural components of pond netting system stressed from snow load





Examples of Damaged Netting and Cables





Failed Structural Posts